Nokia Bb5 Contact service Problem Reason...... and solution.....

SX4: SX4 Smart Card, is a tool or method which is developed by Nokia to


write some data protection for a specific area in EEPROM is useful for

preventing modification of the data.

When SX4 PROCESS is Required ?

In the case of a loss (data corrupt) data charging (not charging), data

network (no network). Dll.RF calibration calibration-charging.



HOW DO I KNOW THAT MY PHONE PROCESS SX4 needs to be done?

When the phone appears CONTACT SERVICE, CONTACT retailers, NOT

charging after flashing, no network, etc. When the SELF TEST is done by

using the box like JAF repair, etc. will be obtained is the result of failed "ST_SECURITY_TEST

Failed".

How do I make a SX4?

Plug the phone in the repair box (JAF, MTBOX, MXKEY, etc.)

Write pm area with 309 results read from the normal mobile phone or can

also write FULL PM area without 308 (SIMLOCK area).

What to do sx4 without internet connection?

sure Certificate damaged area musti made first with the FLASH erase, or

write RPL blank

Reset NPC (when using mxkey)

What is a Certificate Area?

Press info on the box like JAF flasher, etc. and see the results LOG ...

This is an example of the correct Certificate



IMEI plain: 351862xxxxxxxxx

IMEI spare to net: 3A 15 68 02 01 23 60 03

IMEI SV to net: 33 15 68 02 01 23 60 03 F6

LOCK STATUS:

Config KEY: 000000000000000

Provider KEY: 244070000000000

Provider: AT &T; U.S.A. (3650)

Key Code count: 0, FBUS Code count: 0

Block 1:Lock 1: OPEN Lock 2: OPEN Lock 3: OPEN Lock 4: OPEN Lock 5: OPEN

Block 2: Lock 1: OPEN Lock 2: OPEN Lock 3: OPEN Lock 4: OPEN Lock 5: OPEN

Block 3: Lock 1: OPEN Lock 2: OPEN Lock 3: OPEN Lock 4: OPEN Lock 5: OPEN

Block 4: Lock 1: OPEN Lock 2: OPEN Lock 3: OPEN Lock 4: OPEN Lock 5: OPEN

Block 5: Lock 1: OPEN Lock 2: OPEN Lock 3: OPEN Lock 4: OPEN Lock 5: OPEN



Block 7: Lock 1: OPEN Lock 2: OPEN Lock 3: OPEN Lock 4: OPEN Lock 5: OPEN

This is an example Certificate of damaged

Default SN type:

Code:

IMEI plain: 123456765321?

LOCK STATUS:

Block 1: Lock 1: CLOSED

BB5 Contact Service, Restart Problem, How To Erase BB5, Restore PM and RPL Backup!!!

I saw here many times peoples are having with this "Contact Service or Provider" problem

and also unable to Write or Restore the Orignal backup to the Phone. just follow and learned how to repair BB5 Contact Service/Retailer, how to erase BB5 and Restore PM and RPL Backup!!! Now we shall more reflect upon this matter;- How To Remove Contact Service or Provider ?

Firstly we should get Phone Info and see Imei and SL (Sim Lock) Zone are damaged or Not.Get Phone

In Case when you got Damaged Imei: 123456789012345 and you dont have Orignal RPL Backup

then free way is try to solve this problem by downgrading if Imei and SP Data is still damage,

then Upgrade it back and you must need to buy an new RPL to fix this problem. Use ASK to RPL Service.

In Case when Phone Imei is oK but Only SL Zone is damaged and you don't have Orignal PM 308 backup then wat to do.If Courpted SP Data looks like this below:

CONFIG KEY: FFFFFFFFFFFFFFFFF

PROVIDER KEY: FFFFFFFFFFFFFFF

Provider: Unknown provider

And phone is supported for Unlocking, then you can try to Repair it free with any BB5 Unlocker by Unlock Button or with Repair SP Data Option. (It should Repair) Otherewise you may need to New RPL.

And If Courpted SP Data looks like this:

CONFIG KEY: 000000000000000

PROVIDER KEY: 000000000000000

Provider: Unknown provide


Then you must need to buy an New RPL whether Phone is supported with any BB5 Unlocker.

We can not Repair it free, Use Ask To Rpl Service.In Case when you have RPL Backup and have not PM 308, you can only Restore the Phone Imei but you can not Repair the Courpted SP Data like this: PROVIDER KEY: 0000000000000,

Provider: Unknown provide In Case when you have PM 308 backup and have not RPL, you can Repair SP Data but you can not Repair Phone Imei by only PM 308 backup. Use ASK To RPL Service.

In Case when Phone Imei and SL Zone both are OK but phone is still on Contact

Service/Provider.



And if ST Security Test is Failed then Write PM Field [1] And [309] as stanner said,

(or full pm as you wish) by using SX4 Auth Service and after that make Factory Setting.

Oftenly Phone can Repair by Downgrading and Writing RPL.

Then Write PM With SX4 if same then Update back and See problem is Solved or not.

(It should work now!) otherwise try to repair it by erasing method.

Ву

Sameer M T M

MOBIZONE

MOB:9947608585

mail:amalsha_mtm@yahoo.com

www.mobizonetips.co.cc